## **ABSTRACT**

Defects are automatically detected in an image scanning device by performing a defect calibration scan of an image scanning area and detecting at least one defect in at least one section of the image scanning area. A tag is generated for the section of the image scanning area in which the defect is detected. The defect is compensated for in the scanned image based on information contained within the tag.